



Dart Hawkesbury
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D412-750-142
Job Sheet 168404



Part No: D412-750-142

Job Qty: 1 ea

Part Name: Tail Light Fairing RH



CHG001

Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 11/14/17

Job Tracking No:

Due Date: 11/20/17

Created By: Linda Lacelle

Type: SOLD

Description:

Customer: Pacific Helicopters Pty - Asia Pacific (CPACI02)

PO Box 342, Goroka, Eph Papua, , 441 Papua New Guinea ph:011 675 732 1833 fx:011 (675) 5321503.

Note: DWG REV A IPP revA 06.09.22 new issue EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	11/20/17	11/20/17	0.00	0.00	Start Up Stores/Pkg-1		
110	Packaging	1 pcs	11/20/17	11/20/17	0.00	0.00	Packaging1		
120	QC	1 pcs	11/20/17	11/20/17	0.00	0.00	QC4		
125	DC	1 pcs	11/20/17	11/20/17	0.00	0.00	DC		
130	Packaging	1 pcs	11/20/17	11/20/17	0.00	0.00	Packaging3		
140	QC21-FG	1 Ea	11/20/17	11/20/17	0.00	0.00	QC21		

NOV 15 2017

Job Allocations

Operation	Component Part	Required	Inventory	Allocated	Std Qty
90-Start up Operation	AN3-3A 5009891	18 (30)	194	0	0
	D3484-042 5009885	4 (6)	6	0	0
	NAS1149D0363J 5009878	40 (60)	499	0	0

Part Specifications

Specifications could not be found.

Plex 11/14/17 11:45 AM dart.lacelle.linda

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td style="width: 15%;">Skid-tube ☐</td> <td style="width: 15%;">Cross tube ☐</td> <td style="width: 15%;">Water Jet ☐</td> <td style="width: 15%;">Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>				Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐																							
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																																								
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																																								
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																																								
Large Fab ☐	Composite ☐	Supplier ☐																																									
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval																																							
Description Work Order C		 S009901 Tail Light Fairing RH Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K6A 1K7 CANADA TEL.: 1 613 632-5200 Email: sales@dartaero.com www.dartaerospace.com																																									
PART NO: Revision: Operation: Change No:		D412-750-142		Start up Operation																																							
		Mfg Date: 11/14/17 Job No: 168404																																									
		<table style="width: 100%;"> <tr> <td style="width: 50%; vertical-align: top;"> Root Cause <table style="width: 100%;"> <tr><td>Environment ☐</td><td>No Re-verification ☐</td></tr> <tr><td>Design ☐</td><td>Operator ☐</td></tr> <tr><td>Doc/Data ☐</td><td>Offset/Setup ☐</td></tr> <tr><td>Equip/Tooling ☐</td><td>Supplier ☐</td></tr> <tr><td>Handling/Pre ☐</td><td>Training ☐</td></tr> <tr><td>Material ☐</td><td>Use for Testing ☐</td></tr> <tr><td>Internal Transport ☐</td><td>Poor Information ☐</td></tr> <tr><td>Tribal Knowledge ☐</td><td>Rushing ☐</td></tr> <tr><td>LOA ☐</td><td>Product Improvement ☐</td></tr> <tr><td>Substation ☐</td><td>Process Improvement ☐</td></tr> <tr><td>Past Expiry Date ☐</td><td>Manufacturing Process ☐</td></tr> <tr><td>Misidentified ☐</td><td>Past Due ☐</td></tr> </table> </td> <td style="width: 50%; vertical-align: top;"> <table style="width: 100%;"> <tr><td>☐ Cracks</td><td>☐ Inspection</td></tr> <tr><td>☐ Crimp/Kink/Ripple/Wave</td><td>☐ Contamination</td></tr> <tr><td>☐ Cuffs</td><td>☐ Countersink</td></tr> <tr><td>☐ Crushing</td><td>☐ Cut Too Short</td></tr> <tr><td>☐ Heat Treat</td><td>☐ Instructions Incomplete/Unclear</td></tr> <tr><td>☐ Wave/Twist in Tube</td><td>☐ Drill Holes</td></tr> <tr><td>☐ Marks/Chatter</td><td></td></tr> </table> </td> </tr> </table>				Root Cause <table style="width: 100%;"> <tr><td>Environment ☐</td><td>No Re-verification ☐</td></tr> <tr><td>Design ☐</td><td>Operator ☐</td></tr> <tr><td>Doc/Data ☐</td><td>Offset/Setup ☐</td></tr> <tr><td>Equip/Tooling ☐</td><td>Supplier ☐</td></tr> <tr><td>Handling/Pre ☐</td><td>Training ☐</td></tr> <tr><td>Material ☐</td><td>Use for Testing ☐</td></tr> <tr><td>Internal Transport ☐</td><td>Poor Information ☐</td></tr> <tr><td>Tribal Knowledge ☐</td><td>Rushing ☐</td></tr> <tr><td>LOA ☐</td><td>Product Improvement ☐</td></tr> <tr><td>Substation ☐</td><td>Process Improvement ☐</td></tr> <tr><td>Past Expiry Date ☐</td><td>Manufacturing Process ☐</td></tr> <tr><td>Misidentified ☐</td><td>Past Due ☐</td></tr> </table>	Environment ☐	No Re-verification ☐	Design ☐	Operator ☐	Doc/Data ☐	Offset/Setup ☐	Equip/Tooling ☐	Supplier ☐	Handling/Pre ☐	Training ☐	Material ☐	Use for Testing ☐	Internal Transport ☐	Poor Information ☐	Tribal Knowledge ☐	Rushing ☐	LOA ☐	Product Improvement ☐	Substation ☐	Process Improvement ☐	Past Expiry Date ☐	Manufacturing Process ☐	Misidentified ☐	Past Due ☐	<table style="width: 100%;"> <tr><td>☐ Cracks</td><td>☐ Inspection</td></tr> <tr><td>☐ Crimp/Kink/Ripple/Wave</td><td>☐ Contamination</td></tr> <tr><td>☐ Cuffs</td><td>☐ Countersink</td></tr> <tr><td>☐ Crushing</td><td>☐ Cut Too Short</td></tr> <tr><td>☐ Heat Treat</td><td>☐ Instructions Incomplete/Unclear</td></tr> <tr><td>☐ Wave/Twist in Tube</td><td>☐ Drill Holes</td></tr> <tr><td>☐ Marks/Chatter</td><td></td></tr> </table>	☐ Cracks	☐ Inspection	☐ Crimp/Kink/Ripple/Wave	☐ Contamination	☐ Cuffs	☐ Countersink	☐ Crushing	☐ Cut Too Short	☐ Heat Treat	☐ Instructions Incomplete/Unclear	☐ Wave/Twist in Tube	☐ Drill Holes
Root Cause <table style="width: 100%;"> <tr><td>Environment ☐</td><td>No Re-verification ☐</td></tr> <tr><td>Design ☐</td><td>Operator ☐</td></tr> <tr><td>Doc/Data ☐</td><td>Offset/Setup ☐</td></tr> <tr><td>Equip/Tooling ☐</td><td>Supplier ☐</td></tr> <tr><td>Handling/Pre ☐</td><td>Training ☐</td></tr> <tr><td>Material ☐</td><td>Use for Testing ☐</td></tr> <tr><td>Internal Transport ☐</td><td>Poor Information ☐</td></tr> <tr><td>Tribal Knowledge ☐</td><td>Rushing ☐</td></tr> <tr><td>LOA ☐</td><td>Product Improvement ☐</td></tr> <tr><td>Substation ☐</td><td>Process Improvement ☐</td></tr> <tr><td>Past Expiry Date ☐</td><td>Manufacturing Process ☐</td></tr> <tr><td>Misidentified ☐</td><td>Past Due ☐</td></tr> </table>	Environment ☐	No Re-verification ☐	Design ☐	Operator ☐	Doc/Data ☐	Offset/Setup ☐	Equip/Tooling ☐	Supplier ☐	Handling/Pre ☐	Training ☐	Material ☐	Use for Testing ☐	Internal Transport ☐	Poor Information ☐	Tribal Knowledge ☐	Rushing ☐	LOA ☐	Product Improvement ☐	Substation ☐	Process Improvement ☐	Past Expiry Date ☐	Manufacturing Process ☐	Misidentified ☐	Past Due ☐	<table style="width: 100%;"> <tr><td>☐ Cracks</td><td>☐ Inspection</td></tr> <tr><td>☐ Crimp/Kink/Ripple/Wave</td><td>☐ Contamination</td></tr> <tr><td>☐ Cuffs</td><td>☐ Countersink</td></tr> <tr><td>☐ Crushing</td><td>☐ Cut Too Short</td></tr> <tr><td>☐ Heat Treat</td><td>☐ Instructions Incomplete/Unclear</td></tr> <tr><td>☐ Wave/Twist in Tube</td><td>☐ Drill Holes</td></tr> <tr><td>☐ Marks/Chatter</td><td></td></tr> </table>	☐ Cracks	☐ Inspection	☐ Crimp/Kink/Ripple/Wave	☐ Contamination	☐ Cuffs	☐ Countersink	☐ Crushing	☐ Cut Too Short	☐ Heat Treat	☐ Instructions Incomplete/Unclear	☐ Wave/Twist in Tube	☐ Drill Holes	☐ Marks/Chatter					
Environment ☐	No Re-verification ☐																																										
Design ☐	Operator ☐																																										
Doc/Data ☐	Offset/Setup ☐																																										
Equip/Tooling ☐	Supplier ☐																																										
Handling/Pre ☐	Training ☐																																										
Material ☐	Use for Testing ☐																																										
Internal Transport ☐	Poor Information ☐																																										
Tribal Knowledge ☐	Rushing ☐																																										
LOA ☐	Product Improvement ☐																																										
Substation ☐	Process Improvement ☐																																										
Past Expiry Date ☐	Manufacturing Process ☐																																										
Misidentified ☐	Past Due ☐																																										
☐ Cracks	☐ Inspection																																										
☐ Crimp/Kink/Ripple/Wave	☐ Contamination																																										
☐ Cuffs	☐ Countersink																																										
☐ Crushing	☐ Cut Too Short																																										
☐ Heat Treat	☐ Instructions Incomplete/Unclear																																										
☐ Wave/Twist in Tube	☐ Drill Holes																																										
☐ Marks/Chatter																																											
<table style="width: 100%;"> <tr><td>☐ Positioned Wrong</td></tr> <tr><td>☐ Outside Dimensions</td></tr> <tr><td>☐ Over/Under tolerance</td></tr> <tr><td>☐ Part Incorrect</td></tr> <tr><td>☐ Part Lost/Missing</td></tr> <tr><td>☐ Part Moved</td></tr> <tr><td>☐ Drawing</td></tr> <tr><td>☐ Finish</td></tr> <tr><td>☐ Misread</td></tr> <tr><td>☐ Turning Sequence</td></tr> </table>				☐ Positioned Wrong	☐ Outside Dimensions	☐ Over/Under tolerance	☐ Part Incorrect	☐ Part Lost/Missing	☐ Part Moved	☐ Drawing	☐ Finish	☐ Misread	☐ Turning Sequence																														
☐ Positioned Wrong																																											
☐ Outside Dimensions																																											
☐ Over/Under tolerance																																											
☐ Part Incorrect																																											
☐ Part Lost/Missing																																											
☐ Part Moved																																											
☐ Drawing																																											
☐ Finish																																											
☐ Misread																																											
☐ Turning Sequence																																											
OTHER : _____																																											

- 3.8 Fasten the D3484-041/-042 Tail Light Fairing complete with A2064-1683 Tail Light Assembly to the tailboom using the provided (10) AN3-3A bolts into the tailboom's existing holes. Torque bolts 15-25 lb-in (1.7-2.8 N-m). Refer to Figure 1, Detail A.

4.0 WEIGHT AND BALANCE

The following is the net weight increase associated with the installation of the D412-750-141/-142 Tail Light Fairing Kit.

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
D412-750-141 <i>Tail Light Fairing Kit, LH</i>	0.13 lb 0.06 kg	6.0 in 0.2 m	0.78 lb-in 0.01 kg-m	296.1 in 7.5 m	38.49 lb-in 0.45 kg-m
D412-750-142 <i>Tail Light Fairing Kit, RH</i>	0.13 lb 0.06 kg	6.0 in 0.2 m	0.78 lb-in 0.01 kg-m	296.1 in 7.5 m	38.49 lb-in 0.45 kg-m

5.0 PARTS LIST

Qty – 141	Qty – 142	Part Number	Description
X		D412-750-141	TAIL LIGHT FAIRING KIT, LH
	X	D412-750-142	TAIL LIGHT FAIRING KIT, RH
1		D3484-041	TAIL LIGHT FAIRING ASS'Y, LH
	1	D3484-042	TAIL LIGHT FAIRING ASS'Y, RH
10	10	AN3-3A	BOLT
10	10	AN960JD10	WASHER